

CISCOCCNA认证考试640-810题库原题5 PDF转换可能丢失图片或格式，建议阅读原文

https://www.100test.com/kao_ti2020/142/2021_2022_CISCOCCNA_E8_c101_142253.htm Two routers named TestKing1 and

TestKing2 are connected via their serial interfaces as illustrated, but they are unable to communicate. The TestKing1 router is known to have the correct configuration. Given the partial configurations, identify the fault on the TestKing2 router that is causing the lack of connectivity. A. Incomplete IP address B. Insufficient bandwidth C.

Incorrect subnet mask D. Incompatible encapsulation E. Link

reliability too low F. IPCP closed Answer: D Explanation: HDLC and PPP Configuration HDLC and PPP configuration is

straightforward. You just need to be sure to configure the same

WAN data-link protocol on each end of the serial link. Otherwise, the routers will misinterpret the incoming frames, because each

WAN data-link protocol uses a different frame format. Other than configuring some optional features, that 's all you need to do.

100Test 下载频道开通，各类考试题目直接下载。详细请访问 www.100test.com