

国际商务师业务外语辅导：塑胶产品负面描述的英文词汇
国际商务师考试 PDF 转换可能丢失图片或格式，建议阅读原文
https://www.100test.com/kao_ti2020/645/2021_2022__E5_9B_BD_E9_99_85_E5_95_86_E5_c29_645392.htm id="swas"
class="wsww"> blister 起泡 blooming 起霜 blow hole 破孔 blushing 泛白
body wrinkle 侧壁皱纹 breaking-in 冒口带肉 bubble 膜泡 burn mark 糊斑
burr 毛边 camber 翘曲 cell 气泡 center buckle 表面中部波皱 check 细裂痕
checking 龟裂 chipping 修整表面缺陷 clamp-off 铸件凹痕 collapse 塌陷
color mottle 色斑 corrosion 腐蚀 crack 裂痕 crazing 碎裂 crazing 龟裂
deformation 变形 edge 切边碎片 edge crack 裂边 fading 退色 filler speak 填充料斑
fissure 裂纹 flange wrinkle 凸缘起皱 flaw 刮伤 flow mark 流痕 galling 毛边
glazing 光滑 gloss 光泽 grease pits 污斑 grinding defect 磨痕 haircrack 发裂
haze 雾度 incrustation 水锈 indentation 压痕 internal porosity 内部气孔
mismatch 偏模 mottle 斑点 necking 缩颈 nick 割痕 orange peel 橘皮状表面缺陷
overflow 溢流 peeling 剥离 pit 坑 pitting corrosion 点状腐蚀 plate mark 模板印痕
pock 麻点 pock mark 痘斑 resin streak 树脂流纹 resin wear 树脂脱落 riding 凹陷
sagging 松垂 saponification 皂化 scar 疤痕 scrap 废料 scrap jam 废料阻塞
scratch 刮伤/划痕 scuffing 深冲表面划伤 seam 裂痕 shock line 模口挤痕
short shot 充填不足 shrinkage pool 凹孔 sink mark 凹痕 skin inclusion 表皮折迭
straightening 矫直 streak 条状痕 surface check 表面裂痕 surface roughening 橘皮状
表皮皱折 surging 波动 sweat out 冒汗 torsion 扭曲 warpage 翘曲 waviness 波痕
webbing 熔塌 weld mark 焊痕 whitening 白化 wrinkle 皱纹 missing part 漏件
wrong part 错件 excessive defects 过

多的缺陷 critical defect极严重缺陷 major defect主要缺陷 minor defect次要缺陷 not up to standard不合规格 dimension/size is a little bigger尺寸偏大(小) cosmetic defect外观不良 slipped screwhead/slippery screw head螺丝滑头 slipped screwhead/shippery screw thread滑手 speckle斑点 mildewed=moldy=mouldy发霉 rust生锈 deformation变形 burr(金属) flash(塑件)毛边 poor staking铆合不良 excesssive gap间隙过大 grease/oil stains油污 inclusion杂质 painting peel off脏污 shrinking/shrinkage缩水 mixed color杂色 scratch划伤 (Flow Line) 流痕 (Weld Line) 熔接线 Sink Mark凹陷 Streak条纹 Warpage翘曲 欢迎进入：2010年国际商务师课程免费试听 更多信息请访问：百考试题论坛国际商务师 100Test 下载频道开通，各类考试题目直接下载。详细请访问 www.100test.com