

服装样衣及服装英语缩写 PDF转换可能丢失图片或格式，建议阅读原文

https://www.100test.com/kao_ti2020/476/2021_2022__E6_9C_8D_E8_A3_85_E6_A0_B7_E8_c67_476123.htm

bulk sample 货前样，[粤]先行办
counter sample 对等样品，回样
fitting sample 试身样
initial sample，proto sample 原样，初样，[粤]原办，头办
photo sample，press sample 照相样，[粤]影相办
PP sample=pre-production sample 产前样，大货样，[粤]产前办
salesman sample 销售样，[粤]大办，行街办
show room sample 展示样
shipment sample，shipping sample 船头样，[粤]船头办
size set sample 跳码样，[粤]齐码办
test sample 测试样，[粤]测试办
mock-up 局部样
A amp. Efird, Inc. 美国线业公司
A/H，A.H.=armhole 袖窿，[粤]夹圈
a/c，acc.=account 帐单，账目
a/w.，aw=actual weight 实际重量
ABS=area bounded staple fabric 面粘非织造布
add.=address 地址
ADL=acceptable defect level 允许疵点标准
agt.=agent 代理商，代理人
amt.=amount 总计，合计，总额
AOP=all over printing 全身印花
approx.=approximately 约计
AQL=acceptable quality level 质量接受标准
ar.=around 大约
art.=article [欧洲]款式
asap.=as soon as possible 尽快
ATTN.=attention 注意，收件人
aud.=audit 稽核
av.=average 平均
awb. no.=air way bill no. 运单号
B.=back 后
B.=bust (女) 胸围
B.L.=back length 后长
B.N.P.=back neck point 后颈点
B.P.=bust point 胸高点，乳峰点
B.T.=bust top 乳围
B.W.=back width 后背宽
b/l=bill of lading 提单，提货单
bk.=black 黑色
BMS.=body measurement system 人体尺寸测量系统
BMT.=basic motion time 基本动作时间
BNL.=back neckline

后领口BNP , BNPT.=back neck point 后颈点BOC.=band of china 中国银行BOM=bill of material 物料表BP=backpack 背包BRT=barrier removal team 障碍排除小组BSP.=back shoulder point 后肩颈点BTM.=bottom 下摆BTN.=button 钮扣bx.=boxes 箱 , 盒c.amp.F=coat and freight 离岸加运费价格CFT=cross function team 跨功能小组C.P.L.=collar point length 领尖长C.V.C.=chief value of cotton 以棉为主的混纺物c/d.=certificate of delivered 交货证明书C/O , C.O.=country of origin 原产国 , 产地证c/o label , coo. label=country of origin label 产地唛CAD=computer aided design 电脑辅助设计CAE=computer aided engineering 电脑辅助工程CAL=computer aided layout 电脑辅助排料CAM=computer aided manufacture 电脑辅助制造CAP=computer aided pattern 电脑辅助画样ca.=circa 大约cat.=catalogue (产品) 目录cbd.=cash before delivery 付款交货CBL.=center back line 后中线CBM=cubic meter 立方米CBN-W=center back neck point to waist 后颈点至腰CECF=chine export commodities fair 中国出口商品交易会 (广交会) cell.=cellular phone 手机cert.=certificate 证书 , 执照CFS.=container freight station 走拼箱CI=corporate identify 企业标识CIF=cost , insurance amp. k.=damaged amp. hangtag 唛头和吊牌LCL.=loose/less container loading 拼柜LOA.=length over all 全长LSAW.=left side as weared穿起计左侧骨M.=medium 中码M/B=must be 必须M/C=machine 机械mat.=material 物料meas.=measurement 尺寸mkt.=market 市场MLB=Major League Baseball 美国全国棒球协会和盟国棒球协会mmts.=measurements 尺寸mop.=mother of peral 贝壳钮n. to

w.=n.-w.=nape to waist 腰直（后颈点到腰线的距离）n.=neck
领，颈n.p.=neck point 肩颈点n.s.p.=neck shoulder point 颈肩
点N/A=not available 资料不全，信息不全N.Y.=New York 纽
约NYC=New York City 纽约市ndl.=needle 针nil.=nothing
无nk.=neck 颈圈o.s.=outside seam 外长O/L=overlock 拷边，锁
边，[粤]骨o/n=order no. 订单号OJT.=on-the-job training 在职
培训OPA=outward processing arrangement，在中国大陆做裁剪
、零碎件的车缝、整烫、包装。埋夹等主要工序在HK完成。
这样就可算是Made in HK。OPT.=option 选项os.=over size 超
大号OWA=outlook web accessovrlk.=overlock 拷边，锁边，[
粤]骨p.o. no.=production order no. 生产制造单编号p.o.b.=post
office box 邮箱p.p.=paper pattern 纸样PPS，p.p.
sample=pre-production sample 产前样P.S.I.=per square inch 每平
方英寸p.w.=point width 乳间宽，乳中pb.=private brand 个人商
标pc.=price 价格PC=piece 件，个pcs.=pieces 件，个（复数
）pkg.=package 包装pkt.=pocket 口袋pls.=please
请pt.=pnt.=point 点PO=purchase order 订购
单P-O-R=product-o-rial system 吊挂系统pos.=position 位
置px.=price 价格，价钱QC=quality control 质量控
制QC=quality controller 质量控制员QLY.=quality 质
量QPL.=qualified products list 合格产品目录QTY.=quantity 数
量R.=right 右RRP=recommended retail price 建议零售
价R.S.=right side 正面R.T.W.=ready to wear 成衣ref.=reference 参
考，参照rej.=reject 拒绝RVRT=revert 回复rm.=room 场
所rn.=reference number 参考号S=small 小码s.=sleeve
袖S.A.=seam allowance 缝头，缝份，[粤]止口，子

□SNP.=shoulder neck point 肩颈点S.P.=shoulder point 肩点，肩端点S.P.I.=stitch per inch 每英寸针数S.P.M.=stitch per minute 每分钟线迹数s.s.=sleeve slope 肩斜S.S.P.=shoulder sleeve point 肩袖点s/b=should be 应该S/O=strike off 印花样，手刮样s/s=short sleeve 短袖s/y=sample yardagesgl. ndl.=single needle 单针sku.=stock keeping unitslv.=sleeve 袖子spl.=simpl.=sample 样衣，样品，[粤]办snl.=single 单，一个spec.=specification 规格sq.ft.=square feet 平方英尺sty.=style 款式sz.=size 尺码t-s=t-shirt T恤t/p=teck pack 技术档案。客人给你做样板的资料，通常包括款式图、工艺要求、尺寸等。t/s=top stitch 明线t/t=telegraphic transfer 电汇TBA=to be advised 待复TBC=to be confirmed 待确认TBD=to be determined，to be decided 待定THC=terminal handling charges TIT=tone in tone 同色调配色。色系指的是不同的颜色群组，如红色系（大红，粉红，桃红等等）、蓝色（天蓝，水蓝等等）。TOT=tone on tone 同色系配色。色调指的是颜色给人的感觉，如冷色调（淡蓝色等）和暖色调（红色等）。TQC=total quality control 全面质量控制TQM=total quality management 全面质量管理upc=universal product code 通用产品码，通用货单代码W=woven 梭织w.=waist 腰围w.=width 宽度w.b.，w/b=waistband 裤头W.I.P.=work in process 半成品W.S.=wrong side 反面w/=with W/O=without 没有，不W/R=water repellent 防泼水，拨水W/P=waterproof 防水WHK=whisker（洗水）猫须WMSP.=workmanship 手工，车工wt.=weight 重量XL=extra large 加大号，特大号XXL=extra extra large 超特大号yd.=yardage 码数PET，PETE=polyethylene terephthalate 聚对苯二甲酸乙二醇酯HDPE，PE-HD=high

density polyethylene 高密度聚乙烯 PVC=polyvinyl chloride 聚氯乙烯
LDPE , PE-LD=low density polyethylene 低密度聚乙烯
PP=polypropylene 聚丙烯 PS=polystyrene 聚苯乙烯 100Test 下载频道开通，各类考试题目直接下载。详细请访问
www.100test.com