

不插网线终端缓慢的问题解决办法Linux认证考试 PDF转换可能丢失图片或格式，建议阅读原文

https://www.100test.com/kao_ti2020/645/2021_2022_E4_B8_8D_E6_8F_92_E7_BD_91_E7_c103_645016.htm 使用Smartarm3250 V1.00版源码，会出现不插入网线，终端会很缓慢的BUG，可以修改drivers/net/lpc32xx_mii.c文件的下面两个函数解决，将两个函数中的变量的lps的值改为5即可：/* * MACgt.PHY support functions */ static int lpc32xx_mdio_read(struct mii_bus *bus, int phy_id, int phyreg) { struct netdata_local *pldat = bus->net_base). __raw_writel(MCMD_READ, ENET_MCMD(pldat->net_base)). while ((lps & amp; (MIND_BUSY | MIND_MII_LINK_FAIL))) { msleep(1). tmp = __raw_readl(ENET_MIND(pldat->net_base)). __raw_writel(0, ENET_MCMD(pldat->net_base)). return lps. } 100Test 下载频道开通，各类考试题目直接下载。详细请访问

www.100test.com